

Service Bulletin

Subject: FreshBlender - Blown Auxiliary Board Fuse

SCOPE : ALL MODELS FB081TF



SYMPTOM

- LED lights are OFF in drink dispense/blending area
- Ice maker stuck in continuous operation.

ACTION

STORE LEVEL

If the lights are off in drink dispense/blending area;

1. Using the rocker switch on the upper right of the machine, turn unit power OFF.
2. Wait 30 seconds and toggle power back ON.
3. Then wait until the shuttle auto calibrates after startup to see if lights in the drink dispense/blending area illuminate.
4. If lights fail to illuminate after power cycle and shuttle calibration, turn unit power OFF, move all product to a refrigerator, and call to schedule service.

Important

Never leave product in a machine that has been shutdown!

TECHNICIANS

1. Verify the lights do not come on following the store level actions.
2. If lights fail to illuminate, then turn unit power OFF and check for blown fuses in fuse holders of the Auxiliary and SRB circuit boards.
3. If fuse(s) are bad or blown, replace fuse(s) and complete the light illumination check step again after re-powering unit.

Important

The unit should always be powered off when changing any electrical component to avoid shock and/or damage to other electrical components!

FURTHER ACTIONS

Technicians, please note if ever replacing solenoids on the water manifolds, make sure any residual moisture or water is cleaned off the solenoids and no leaks are present before re-powering unit. Water left on any solenoid harness can cause arcing and contribute to blown fuses.

Contact Welbilt KitchenCare if you have any questions or concerns: 1-844-724-CARE (2273).